


**South Bethany relieved damage not worse
Ground-level houses on west flooded, but none are floating
News Journal October 31,2012**



Photo by Robert Craig

Area Flooded by Sandy on 10/29/2012 – Shown in Yellow



The water in the canals rose to 5.44 feet NGVD on the South Bethany Tide Gage at about midnight on 10/29/2012. This flooded many ground floors to a depth of about 2 feet. See next picture.

Note water level line shown on homes.

